

# Upgrading and dividing cabins on a platform in the North Sea



REFERENCES FOR PROJECT  
*January 2019*


## CUSTOMER

Leading offshore operator  
in the North Sea

## THE PROJECT

Background: Leakage on main pipe for water supply has caused a critical water damage on a cabin floor. Seacabin Offshore was involved all through the process from cleaning the area to installation of a brand-new cabin – divided into two separate rooms.

A true turn key solution for our clients including technical solution, design, materials, installations also electrical installations.



## WE ASSIST ON

- Technical inspection – for clarifications of the extent after water damage
- Cleaning after water damage
- Various design solution for renovation of the cabin including cabin split
- Project description, permit preparations and planning all preparation for the project execution offshore
- Project execution from relocation of firewater hose, moving entrance door to a full finish cabin split including carpenter work, electrical installations and HVAC trades
- Documentation and project close-out



## CONTACT US

Tlf. +45 69 14 14 70  
ahu@seacabinoffshore.dk  
www.seacabinoffshore.dk

**SEACABIN**  
OFFSHORE